DMV Lane Technician Observation Report

DMV Technician: //rah RAY Station: 444/M	Position: 1 or 2					
Station: Wilm Date: 3-14-14	Time: 10.20					
Vehicle Make: Honde Model Parale	ehicle Make: Hande Model parale Year 2006					
GVWR: Fuel Type: 6 p 5 Registr						
	Overt (Cir		e)			
		YES	NO	N/A		
1. Did technician check vehicle paper work and verify VIN no	umber?	1				
2. Was Emissions testing required?		V				
a) Was Emissions testing performed using OBD?		1				
b) Was Emissions testing performed using Analyzer Probe?)					
c) Was Emissions testing performed using Paddle(s)?						
d) Was Emissions testing performed using Clip?						
3. Was Catalytic Converter inspection required?				1		
a) Was Catalytic Converter inspection performed?						
4. Was Fuel Tank pressure testing required?				V		
a) Was Fuel Tank pressure testing performed?						
5. Was Fuel Cap pressure testing required?				1/		
a) Was Fuel Cap pressure testing performed?	VVA IIIA ada					
6. Is this test a Re-check from a prior failure?			V			
a) Which re-check test is being performed? 1 2 3 (circle of	one)					
b) If this is re-check #3, was repair paperwork verified for v	vaiver?					
Sussex County Only						
7. Was Curb Idle testing required?						
a) Was Curb Idle testing performed?						
				HOUSE PRINTERS		
Comment:			21 In. 00 Hills	001200 - 1111		
				tealling		
	v					

DMV Lane Technician Observation Report

DMV Technician: Bennifield BOB Posit	Position 1 or 2					
Station: Wilm Date: 3-1474 Time: 10.50 Vehicle Make: Ohry In Model DV Year 2006 GVWR: Fuel Type: 825 Registration Number: 95744 Auditor: Covert/Overt (Circle One)						
Vehicle Make: Ohry Lin Model enz	Z Year 2006					
GVWR: Fuel Type: 625 Registration	GVWR: Fuel Type: 625 Registration Number: 95744					
Auditor: Covert/Overt	or: Co verdy (Circle One)					
	YES	NO	N/A			
1. Did technician check vehicle paper work and verify VIN number?						
2. Was Emissions testing required?						
a) Was Emissions testing performed using OBD?						
b) Was Emissions testing performed using Analyzer Probe?						
c) Was Emissions testing performed using Paddle(s)?						
d) Was Emissions testing performed using Clip?						
3. Was Catalytic Converter inspection required?			-			
a) Was Catalytic Converter inspection performed?						
4. Was Fuel Tank pressure testing required?			1			
a) Was Fuel Tank pressure testing performed?						
5. Was Fuel Cap pressure testing required?			V			
a) Was Fuel Cap pressure testing performed?						
6. Is this test a Re-check from a prior failure?		2				
a) Which re-check test is being performed? 1 2 3 (circle one)						
b) If this is re-check #3, was repair paperwork verified for waiver	r?					
Sussex County Only						
7. Was Curb Idle testing required?						
a) Was Curb Idle testing performed?						
Comment:						

DMV Lane Technician Observation Report

DMV Technician: FITE Harris Densis Position	on: 1 or 2					
	CHEST COLORS	35	_			
Vehicle Make: Chr Model Aughor	Station: Wilm Date: 3 - 14-14 Time: 10:35 Vehicle Make: Chy Model Broken Year					
GVWR: Fuel Type: 645 Registration N		11-	1.6			
Auditor: Courdan Covert/Overt	Circle On	e)	5 €/			
Tradition (bladity)	onere on					
	YES	NO	N/A			
1. Did technician check vehicle paper work and verify VIN number?	1					
2. Was Emissions testing required?	/					
a) Was Emissions testing performed using OBD?						
b) Was Emissions testing performed using Analyzer Probe?						
c) Was Emissions testing performed using Paddle(s)?						
d) Was Emissions testing performed using Clip?						
3. Was Catalytic Converter inspection required?			1_			
a) Was Catalytic Converter inspection performed?						
4. Was Fuel Tank pressure testing required?			_			
a) Was Fuel Tank pressure testing performed?						
5. Was Fuel Cap pressure testing required?			2			
a) Was Fuel Cap pressure testing performed?						
6. Is this test a Re-check from a prior failure?		~				
a) Which re-check test is being performed? 1 2 3 (circle one)						
b) If this is re-check #3, was repair paperwork verified for waiver?						
Sussex County Only						
7. Was Curb Idle testing required?						
a) Was Curb Idle testing performed?						
Comment:						
	:4/					